




WHITE PAPER | JANUARY 2022

# The Three Steps of Tolerance Analysis



The Market Leader in Mechatronics and Detailed Design Services | [simplexitypd.com](https://www.simplexitypd.com)

## INTRODUCTION


Transforming your mechanical CAD designs into a real and tangible parts is one of the most rewarding feelings as an engineer. However, a lot of things can go wrong during this transition. One of the most common and most overlooked problems are tolerances. Have you ever tried mounting your TV on your wall, but the holes don't line up perfectly? Or do you have to jiggle your keys every time you open the front door? These issues occur because of poorly controlled tolerances.

Controlling tolerances is an important part of any designer's responsibility. In applications like optics, precision motion, drive trains, and plastic enclosures, tolerances become extremely important, and the overall design is essentially dictated by tolerance requirements. In this article, we will walk through step-by-step examples and illuminate the path to good tolerancing in your designs.

## TOLERANCES

Mechanical designs and mechanical drawings use a **nominal dimension** to describe a width, height, depth, diameter, or radius on a part so that the part can be built. A **tolerance** is associated with each dimension because as designers, we know that the part will never be 100% atomic-level accurate, but instead can be "close enough" within some range of the nominal dimension.

Tolerances are typically specified using a **symmetric  $\pm$  tolerance zone**. This means that when a part is manufactured, the actual dimension can be some distance more or less than the nominal dimension. Imagine you are designing a microscope fixture. The microscope bottom needs to be 6 mm away from the slide, and the focal range is 0.5 mm wide, so the dimension between the microscope and the slide should be  $6 \pm 0.25$  mm. The tolerance of this dimension is the " $\pm 0.25$  mm" part which means that the



actual measured distance after manufacturing can be 5.75 mm to 6.25 mm. You would likely find this dimension on a list of **design requirements** determined before design even begins or on the microscope data sheet.


Often tolerances specified in parts are driven by the manufacturing methods available. A larger tolerance zone allows the manufacturer to be less strict in how the design is made, and so the design is said to have a **looser tolerance**. On the other hand, a **tighter tolerance** dimension is one that is difficult to achieve because the tolerance zone is so small.

A good mechanical drawing is also likely to have more elements than just dimensions and tolerances. In addition to revision tables, notes, and part numbers, drawings also commonly have hole callouts, fitment callouts, and Geometric Dimensioning and Tolerancing (GD&T) symbols to help the manufacturer understand and produce your design. Although these elements are often important in tolerancing, they are beyond the scope of this article.

## A TOLERANCE “STACK”

Even if the production methods allow you to design tight tolerances on a single part, you need to consider the tolerances of all the parts around it to make sure that the overall system functions correctly.

Let’s revisit the example of the microscope fixture. Our microscope needs to be held at a specific height above a slide, so we plan to design a microscope stand, a slide holder, and a mounting plate for the parts to be mounted on. We know that the microscope needs to be held  $6 \pm 0.25$  mm away from the top surface of the slide, and we plan to machine the parts using a CNC milling machine which has an accuracy of  $\pm 0.2$  mm. The machining tolerance zone is smaller than the required tolerance zone, so no problem, right?



Well, actually no. Each of the parts may be 0.2 mm away from what we want. So, if the microscope stand is 0.2 mm taller after machining, and if the slide holder comes out 0.2 mm thinner, then the slide would actually be 0.4 mm away from the nominal 6.0 mm, causing the image to be out of focus. In a case like this, you would need to do a


**tolerance analysis** of the **tolerance stack-up** to make sure the design will work. A tolerance analysis looks

at all the relevant tolerances in a system and adds them so that we can improve the design to meet a certain design requirement. A tolerance stack-up analysis is usually done on a spreadsheet. Feel free to use this [Tolerance Analysis Template](#) to get started. We will be using this template later in this article to walk through the analysis.

In a product design, a designer would usually conduct two tolerance analyses. An **Architecture Tolerance Analysis** is conducted in the early design stages. In product design, “architecture” generally refers to a high-level design where the details aren’t worked out yet, but the designer can begin to get a sense of what components need to be made or purchased. At Simplexity, this analysis would be conducted during Phase 2A. For more information on our Product Development Process, you can refer to <https://www.simplexitypd.com/resources/product-development-process/>.

The second tolerance analysis, or **Detail Tolerance Analysis**, updates the previous stack-up and confirms the finalized design before release. This update usually occurs during Phase 2B. However, tolerance analyses are typically iterative, and you may also want to update your analysis whenever the manufacturer, material, or architecture changes.

Each time a tolerance analysis is conducted it can generally be split into three steps: **Prepare, Stack, and Adjust** (or PSA). In this article we will walk through these steps for the **Architecture Tolerance Analysis** and the **Detail Tolerance Analysis**.



You don’t need a tolerance analysis for every measurement in the system, so it is up to your design requirements and engineering intuition to gauge when an analysis is needed. As a general Rule-of-Thumb, you should conduct a tolerance analysis when:

1. Two or more parts need to be aligned precisely to ensure function of the assembly, or
2. One or more parts are using “looser tolerance” manufacturing methods.

## ARCHITECTURE TOLERANCE ANALYSIS


Here we will walk through the **Architecture Tolerance Analysis** using the **Prepare, Stack, Adjust** method. This analysis helps you catch any major design issues before spending too much time on detail design. Before starting the analysis, you should already have a rough idea of the part quantities, the manufacturing methods available, and which parts are important. However, if your design is already too detailed with fastening features and drawings, be prepared for some design changes!


## Step 1A: Prepare – Rough Block Diagram

Because tolerance analyses are usually done before detailed design is complete, I highly recommend making a rough block diagram of your system. Basic diagrams clarify important interfaces and dimensions before the design is detailed, and they serve as an important tool for communicating your findings at design reviews.

It's best to put the block diagram right on the tolerance stack spreadsheet, but you can also make blocks in PowerPoint or draw.io. The diagram should only give a general sense of the relevant parts, and not be too detailed.

Some examples:





Returning to our microscope fixture mentioned earlier, the block diagram for this fixture can be put directly on the tolerance analysis spreadsheet as shown below. Fill out the document header with information such as the project, designer, and the goals of this tolerance study.

	A	B	C	D	E	F	G	H
1	Tolerance Analysis Title	Microscope Tolerance Stack						
2	Author	Neil Foxman						
3	Date of Analysis	September 21, 2020						
4	Project	Microscope Inspection Tool						
5	Subsystem	Optics Subsystem						
6	Unit of Measure	mm						
7	Design Objective and Notes	From the microscope datasheet, the lense at the bottom of the microscope needs to be $6 \pm 0.25$ mm away from the top surface of the slide.						
8	Conclusion							
9	Mechanical Design Block Diagram	<p>The diagram shows a side view of a microscope assembly. A black "Microscope" is mounted on a purple "Microscope Stand". Below the microscope is a white "Slide" held in a green "Slide Holder". The slide holder sits on a blue "Mounting Plate". A dimension line indicates the distance from the top surface of the slide to the bottom of the microscope is <math>6.00 \pm 0.25</math> mm.</p>						
10								

### Step 1B: Prepare – Find the Manufacturing Tolerances


Now that you have a better sense of the parts used in the stack, you can start finding each part’s manufacturing tolerances. We may end up specifying different tolerances later, but the goal is to get a rough-order-of-magnitude or “ROM” estimation of each part’s tolerances at this stage to catch if your design is way off and needs larger architectural or manufacturing changes.

I would recommend looking for tolerances on rapid prototyping manufacturer websites. Most prototyping manufacturers automate their process, so they are more likely to post tolerance information online instead of assigning someone to review each customer drawing. For instance, we commonly use Protolabs for machining prototype parts, and they have good design guides with tolerances for [CNC milled parts](#), [CNC turned parts](#), and [sheet metal parts](#).

If you are using off-the-shelf or “OTS” parts, look for part datasheets or drawings that will show you the important dimensions and tolerances.

Let’s now find the relevant tolerances for our microscope fixture example. As we’re preparing our analysis, we will need some tolerance estimates for all parts that determine the vertical distance between the microscope and the slide. So according to our diagram we need tolerances for the microscope, microscope stand, slide holder, and slide. We don’t need to consider the tolerance for the mounting plate as its vertical dimension doesn’t impact the distance between the slide and microscope i.e. if the mounting plate is too thick or too thin, the microscope height above the slide still remains the same.


We will plan to mount the microscope on the microscope stand using some alignment features. Let’s say our microscope has a datasheet that claims the tolerance between the bottom of the microscope and a mounting pin is 0.05 mm. Note that we don’t yet care what the actual dimension is, just the tolerance zone.



Let’s plan to fit the mounting pin on the microscope into a clearance hole on the microscope stand. Looking again at the microscope datasheet, we see that the mounting pin has a diameter of  $3.95 \pm 0.03 \text{ mm}$ . A common ISO 286 tolerance zone for a hole is H7 which has an asymmetric 0.012 mm tolerance zone ( $4.000 +0.012, -0.000 \text{ mm}$ ). For other hole/shaft fits, you can use the tool on [Engineer's Edge](#). This tolerance zone is asymmetric, but we will revisit this fit in the stack phase to see how it can be used.



Next, we can assume that the microscope stand, and slide holder are made using a CNC milling machine, so we would like to find some tolerances for these parts. Looking at our manufacturer website, they claim that their usual machining tolerance is 0.005” (0.13 mm). Again, we don’t need the dimensions as

these parts haven't been designed yet, we just need to know that if we ask the manufacturer to make two features some distance from each other, they can be accurately machined within 0.13 mm.



Finally, the slide thickness will have its own tolerance. Early in the design process, there is often missing information. In this case, we don't yet know if we want the microscope fixture to support a number of slides or just one specific brand, so instead we can do a Google search for glass slide manufacturers and take a rough guess at the slide thickness tolerance assuming we will revisit it later. In this case let's assume we found a slide manufacturer that quotes their thickness to be within 0.13 mm.

Although the microscope fixture uses generally simple part geometries, it's worth noting that you should try to visualize how each part will be made, as some production methods can have vastly different tolerances depending on the part orientation. For instance, sheet metal tolerances between two edges on the same plane can have much tighter tolerances than the dimension between an edge and a bend as shown below. 3D printed parts may also be sensitive to the build orientation. In general, machined parts have tighter tolerances when the part is only held in one orientation, but tolerances increase between features when the part is flipped or moved within the machine. For all these manufacturing methods, smaller dimensions may also have tighter tolerances than larger dimensions.





If you find any tables or web pages you find useful, you may want to copy that information into the bottom section of the spreadsheet for faster analysis and review.

35 Reference Material and Screen Shots	
36	
37	

## Step 2: Stack – Fill out the Tolerance Stack




Now that we have an idea of the relevant part tolerances, it's time to create our Tolerance Stack using the template provided. Let's enter each tolerance found earlier into the spreadsheet. It helps if there is a logical order to the tolerances entered in the spreadsheet, so we will look at each dimension along the way from the bottom of the microscope to the top of the slide.


We first enter the tolerance from the microscope bottom to the microscope mounting pin. Enter the description of the relevant features in the From and To columns and the numerical tolerance on the top line. Ignore the nominal dimension column for this study, and don't change the formulas in the gray columns because these will update automatically. The second section in your tolerance stack should now look like this:

	From	To	Nominal Dimension	Tolerance	% Contribution	Tot*2	Sources, Assumptions, and Calculations
10							
11							
12	Microscope Bottom	Microscope Mounting Pin		± 0.050	100.0%	0.003	
13				±	0.0%	0.000	
14				±	0.0%	0.000	
15				±	0.0%	0.000	
16				±	0.0%	0.000	
17				±	0.0%	0.000	
18				±	0.0%	0.000	
19				±	0.0%	0.000	
20				±	0.0%	0.000	
21				±	0.0%	0.000	
22				±	0.0%	0.000	
23				±	0.0%	0.000	
24				±	0.0%	0.000	
25				±	0.0%	0.000	
26				±	0.0%	0.000	
27				±	0.0%	0.000	
28				±	0.0%	0.000	
29				±	0.0%	0.000	
30							

It's a good idea to be verbose with what dimension you are referring to in the From and To columns so that your thinking can be more clearly communicated to a reviewer and to give yourself a reminder during design.

Next, some care needs to be taken when considering the fitment between the microscope mounting pin and the hole in the microscope holder. Because this is a clearance hole, there can be some misalignment, and we need to consider the worst-case condition for our tolerance stack. In this case, we get a maximum misalignment of the microscope to the microscope holder in the Least Material Condition where the hole is at 4.012 mm and the pin is at 3.92 mm. This means that there is a possible misalignment of 0.046 mm as shown below.





To capture this possible misalignment in our tolerance stack, we need to add another line showing this position tolerance possibly including some notes on how this tolerance was achieved.

From	To	Nominal Dimension	Tolerance	% Contribution	Tol^2	Sources, Assumptions, and Calculations
Microscope Bottom	Microscope Mounting Pin		± 0.050	52.1%	0.003	
Microscope Mounting pin	Microscope Stand hole		± 0.046	47.9%	0.002	Maximum misalignment considered in LMC (4.012 mm hole, 3.92 mm pin)
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	

The rest of the tolerances are machining tolerances between features on the microscope holder, slide holder, and slide. We can enter that information into the spreadsheet as shown. Notice how each dimension is fully described in order from the microscope to the slide.

From	To	Nominal Dimension	Tolerance	% Contribution	Tol^2	Sources, Assumptions, and Calculations
Microscope Bottom	Microscope Mounting Pin		± 0.050	10.3%	0.003	
Microscope Mounting pin	Microscope Stand hole		± 0.046	9.5%	0.002	Maximum misalignment considered in LMC (4.012 mm hole, 3.92 mm pin)
Microscope Stand hole	Microscope Stand bottom surface		± 0.130	26.7%	0.017	
Microscope Stand bottom surface	Slide holder bottom surface		± 0.000	0.0%	0.000	Assuming mounting plate is perfectly flat
Slide holder bottom surface	Slide holder top surface		± 0.130	26.7%	0.017	Slide thickness estimated
Slide bottom surface	Slide top surface		± 0.130	26.7%	0.017	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	

Finally, you can see the total tolerance of the stack in the third section of the spreadsheet.

	Dimension	Tolerance	Lower Limit	Upper	Notes
Arithmetic Stack (Worst Case)	0.000	± <b>0.486</b>	-0.486	0.486	
Statistical Stack (RSS)	0.000	± <b>0.235</b>	-0.235	0.235	
Adjusted Stack (RSS * 1.5)	0.000	± <b>0.353</b>	-0.353	0.353	

For now, the focus of this exercise is the top line of this section: **Arithmetic Stack (Worst Case)**. The value in the tolerance column represents the sum of all the tolerances in the stack. It looks like we will



using 3D printed plastic, consider if the critical alignment features could be replaced by a sheet metal bracket or machined part. Also, you can look for vendors with tighter tolerance specifications as the tolerances are commonly dependent on what tools they have in the shop. Instead of a clearance hole, we can investigate using a press-fit hole to remove the possible misalignment tolerance.


### 3. Consider using or modifying off-the-shelf precision parts

Modifying off-the-shelf parts is also a good cost-cutting method. Instead of designing a custom shaft with really tight tolerances, you may instead choose to machine your features into a stock shaft that you purchase with tight tolerances. For the microscope holder, I would ask the microscope vendor if they supply any mounting brackets that hold tight tolerances or a bracket that can hold the slide to a controlled surface.

### 4. Introduce compliance and float into the system, and perform critical alignment during operation

This concept introduces more complexity to your design, but it is likely to significantly reduce the total tolerance stack of your system. Instead of fixing each part at a single position and making the machining tolerances tight for all the parts, consider allowing most of the parts to have loose tolerances or move in space. Then introduce an engagement step or clamping step where the critical parts are aligned with a single part.

In our microscope holder example, this could be a custom designed Microscope Head that is spring loaded against the top surface of the slide. In this case we don't care as much about the tolerances of the other parts, and only need to control the dimension between the Microscope mount features and the slide surface. Our system and tolerance stack would then look like:



From	To	Nominal Dimension	Tolerance	% Contribution	Tol^2	Sources, Assumptions, and Calculations
Microscope Bottom	Microscope Mounting Pin		± 0.050	22.1%	0.003	
Microscope Mounting pin	Microscope Head hole		± 0.046	20.4%	0.002	Maximum misalignment considered in LMC (4.012 mm hole, 3.92 mm pin)
Microscope Head hole	Microscope Head alignment surface		± 0.130	57.5%	0.017	
Microscope Head alignment surface	Slide Top Surface		± 0.000	0.0%	0.000	Assumed both slide and alignment surfaces are perfectly flat
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
			±	0.0%	0.000	
		Dimension	Tolerance	Lower Limit	Upper	Notes
Arithmetic Stack (Worst Case)		0.000	± <b>0.226</b>	-0.226	0.226	
Statistical Stack (RSS)		0.000	± <b>0.147</b>	-0.147	0.147	
Adjusted Stack (RSS * 1.5)		0.000	± <b>0.220</b>	-0.220	0.220	

We are now within our target tolerance zone! This architecture should work for our design, but it’s worth noting that the complexity has increased: you now have to design the spring mechanism and investigate if the additional forces on the slide cause it to break or warp.

### 5. Revisit the tolerance requirements

Satisfying a requirement may be as easy as changing the requirement itself. Communicating with other team members will likely help you identify how the requirement was originally specified, how strict the requirement is, and if the requirement could be satisfied in an alternative design. Early requirements are often rough guesses, and it helps to quantify how time and costs can be reduced by relaxing a given requirement.

### 6. Use the Statistical Stack, and Adjusted Statistical Stack

So far, we have been using the **Arithmetic Stack (Worst Case)** to determine if the design is feasible. However, it may not be cost effective to design using this metric, and you may choose to instead use the results for the **Statistical Stack (RSS)** or **Adjusted Stack (RSS \* 1.5)** in the lower section. We will discuss these analyses in more detail later in this article.

Sometimes the tolerances are just too tight to design around, and you need to start looking at more expensive operations. Some additional options are listed below.

#### 1. Introduce additional design controls

Adding GD&T tolerance callouts to your drawing adds further control to your design if you know how to use them properly. More design controls generally increase the cost of your parts because they require slower machining speeds, create additional machining steps (like lapping), or introduce inspection steps after manufacturing. However, there are specific callouts for flatness, parallelism, and position that may be able to give minor benefits.

## 2. Alignment/calibration in production

Similar to designing compliance into the system, you can also design the parts with loose tolerances and include an alignment step during production. In general, this means you would design clearance between the critical parts, and then use a single precision alignment fixture to make sure that they are aligned properly before tightening and fastening them into place. Note that this will increase the overall product cost because not only are you designing an additional alignment fixture, but you are also adding labor to the final assembly. This also potentially makes repairs more difficult if any modification requires a re-calibration as well.

## 3. Use Precision Manufacturing methods


There are some specialized tools that allow you to make very precise parts at high cost. For example, Electrical Discharge Machining or EDM will likely be the most precise manufacturing methods available for a mechanical design, but it incurs a significant cost and potential impact to schedule. Some dimensions can be held to an astounding  $\pm 0.001$  mm, and I would recommend looking for some YouTube videos like [this one](#) to gawk at the capabilities. However outside of hyper-precision applications, if you need to use EDM you are likely overlooking some other easier alternatives.

If you need to make architecture or manufacturing changes, repeat the process: **Prepare** and research what the updates entail, add or remove parts in the **Stack**, and **Adjust** the design until the tolerances are reasonable and you can proceed with more detailed design.

## DETAIL TOLERANCES ANALYSIS

The **Detail Tolerance Analysis** is focused on verifying your design tolerances before release. In this stage, the detail design of your system should be almost done, and you revisit your original estimates to get more accurate tolerances. It may help if you have mechanical drawings while filling out the Detail Tolerance Analysis.

To continue our previous example, let's assume that we were able to bring our tolerances within our requirements using the compliant spring concept for our design.










diagonal tolerance stacks. In more complicated cases, I would recommend using conservative estimates or inspecting some test parts to gain more confidence that your tolerance analysis is reasonable.


### Step 3: Adjust – Update the Tolerances on the Mechanical Drawing

A mechanical drawing is a *communication tool* that allows you to specify the important tolerances of your design. If a dimension is in your tolerance analysis, that exact dimension should also be called out in the drawing.

Here, I have dimensioned the distance between the Microscope Head Hole and the Alignment Surface correctly according to the tolerance stack.



In the image below, the dimension has been called out incorrectly because now there are two  $\pm 0.013$  mm tolerances between the Microscope Head Hole and the Alignment Surface.





article is a good refresher on these concepts for those familiar with Statistics:  
<http://www.stat.yale.edu/Courses/1997-98/101/rvmnvar.htm>

You may notice that the spreadsheet also includes a value for the  $RSS \times 1.5$  tolerance zone. The 1.5 is a safety factor used to make the result a little more conservative. This 1.5 value has no mathematical interpretation, but it is commonly used in quality control. To reduce risk, you can edit the formula within the spreadsheet and increase the safety factor.

## CONCLUSION

Our walkthrough of both the **Architecture Tolerance Analysis** and the **Detail Tolerance Analysis** can help serve as a guide when you look at the tolerances of your own designs.

Tolerance analyses don't just apply to mechanical parts; in the engineering world, most measurements are approximate and knowing the tolerances of the components you buy can help you better gauge the performance of the overall system. For example, most electronic components have tolerances associated with their values, or operate within a range of acceptable supply voltages or currents.

Although every project is different, if you remember to **Plan, Stack, and Adjust** during each of your tolerance analyses, you can quantify the total tolerance of your system, and more confidently release your mechanical designs for production.

## ABOUT THE AUTHOR

Neil Foxman is a Senior Systems Engineer at Simplexity's San Diego office. In 2014, he graduated with a Bachelor of Science in Mechanical Engineering from Tufts University and has since taken Electrical Engineering master's degree courses at University of California, San Diego. Since joining Simplexity in 2015, Neil has worked on a variety of mechanical, electrical, and software designs.